

Opel Astra H — O ar condicionado não funciona | HELLA

Opel Astra H
Ano de modelo: 2004–2008
Com sistema automático de climatização (ECC)
O ar condicionado não funciona no modo automático
Nos veículos supramencionados, devido a um “erro no software”, o ar condicionado pode funcionar apenas no modo manual. O ecrã apresenta frequentemente uma mensagem de erro incompreensível (M1–M5). Esta situação pode ser resolvida através de uma atualização do software. O fabricante do veículo já utilizou o software modificado de fábrica em veículos a partir dos seguintes VIN:
W0L0AHL4882160266 — (fábrica de Bochum)
W0L0AHL0885117742 — (fábrica de Antuérpia)
W0L0AHL4888096223 — (fábrica de Ellesmere Port)

Astra H

Model years: 2004 - 2008

With electronic climate control (ECC)

Air conditioning not working in automatic mode

In the above vehicles, "software failure" may be the cause that the air conditioning works only in manual mode. The display will then often show an incomprehensible error message (M1 - M5).

This can be remedied by a software update.

The vehicle manufacturer has already been using the modified software at the factory starting from the following VINS:

W0L0AHL4882160266 - (Bochum plant)

W0L0AHL0885117742 - (Antwerp plant)

W0L0AHL4888096223 - (Ellesmere Port plant)