

Opel Astra J — Código de erro P261A | HELLA

Opel Astra J
Ano de modelo: 2012
Motor: A17DTE/A17DTF
Com bomba do líquido de refrigeração de comando elétrico
Código de erro P261A/A lâmpada de erro da eletrônica do motor (SVS) acende
Nos veículos supracitados, pode acender a lâmpada de erro da eletrônica do motor e pode ser registado o código P261A na memória de erros.
O código de erro é referente à bomba do líquido de refrigeração, que é acionada pelo motor e comandada eletricamente e não à bomba elétrica auxiliar.
Por norma, a bomba do líquido de refrigeração está OK.
Para resolver o problema, deve-se efetuar uma atualização do software do módulo de comando do motor, assim como uma inspeção visual e de funcionamento.

Astra J

Model year: 2012

Engine: A17DTE / A17DTF

With electrically controlled coolant pump

Error code P261A /

Engine management system fault light (SVS) lights up

On the vehicles listed above, the fault light for the engine management system may light up and the code P261A may be stored in error memory.

The error code refers to the electrically controlled coolant pump driven by the engine and not the electrical auxiliary pump.

The coolant pump is usually in working order.

To remedy the error, update the software for the engine control unit and carry out a visual inspection and function check.