

Opel Insignia — Perda de líquido de refrigeração no radiador RGE | HELLA

Opel Insignia Ano de modelo: 2009 - Motor: A20DT/A20DTH/A20DTJ/A20DTR/A20DTC

Perda de líquido de refrigeração no radiador RGE

Nos veículos supramencionados, é possível uma perda de líquido de refrigeração na área do zona do radiador da recirculação dos gases de escape (radiador RGE). Ao verificar o sistema de refrigeração, prestar especial atenção à carcaça do radiador RGE. Esta pode apresentar fissuras, resultando na perda de líquido de refrigeração.

Para resolver a situação, deve-se proceder da seguinte forma e utilizar um kit de reparação (Figura) constituído por uma carcaça, 2 vedantes e 2 clipe:

Deixar arrefecer o motor

Desmontar a carcaça do radiador RGE (recolher o líquido de refrigeração)

Desmontar o radiador RGE da carcaça

Limpar as superfícies vedantes

Utilizar o kit de reparação (ref.: 55590953):

Montar o radiador RGE na nova carcaça

Montar a carcaça do radiador utilizando os novos vedantes

Encher o líquido de refrigeração

Purgar o ar do sistema de refrigeração

Realizar um teste de estanqueidade

Astra J

Model year: 2010 -

Engine: A20DT/A20DTH/A20DTJ/A20DTR

Loss of coolant

The above vehicles can experience a loss of coolant near the exhaust gas recirculation cooler (EGR cooler).

If you suspect a leak in the cooling system, special attention should be paid to the EGR cooler. A crack in the housing can lead to a slow, gradual loss of coolant.

