

Opel Meriva B — O motor não pega | HELLA

OpelMeriva B Ano de fabrico: 2010–2011 VIN: A4000001–B4231542 O motor não pega. Se, no veículo supramencionado, o motor não pegar, tal pode dever-se a uma bomba hidráulica da direção assistida com defeito. Para localizar a origem da avaria neste caso, verificar a comunicação CAN-Bus da direção assistida. Caso não seja possível estabelecer qualquer comunicação, deve proceder-se da seguinte forma. Desconectar o conector o conjunto de cabos da bomba hidráulica (direção assistida). Ligar o motor. Se o motor ligar apesar de o conector o conjunto de cabos estar desconectado, tal pode dever-se a uma bomba hidráulica (direção assistida) com defeito. Para resolver o problema, deve ser instalada uma nova bomba hidráulica.

Meriva B

Model year: 2010–2011

Chassis no.: A4000001 – B4231542

Engine does not start.

If the engine of the vehicle listed above does not start, the cause may be a defective power steering hydraulic pump.

To find the source of the fault in this case, the power steering's CAN bus communication must be checked. Proceed as follows if no communication can be established.

- Disconnect the hydraulic pump's cable harness plug (power steering).
- Start the engine.

If the engine starts although the cable harness plug is disconnected, the cause may be a defective hydraulic pump (power steering).

A new hydraulic pump should be installed to correct the problem.