

Opel Meriva B — Perda de óleo no compressor | HELLA

Opel Meriva B Ano de modelo: 2010–2012 Com ar condicionado Perda de óleo no compressor/Perda de agente refrigerante No caso dos veículos supracitados, podem ocorrer uma fuga no compressor. A fuga de óleo/produto de contraste é normalmente visível. Para resolver o problema, deve-se substituir o compressor por uma variante modificada: Ref. antiga: Será substituída pela nova ref. 13 271 264 13 395 696 13 271 266 13 395 693 13 271 267 13 395 694 13 271 268 13 395 695 13 271 269 13 395 696 A partir do ano de modelo 2012 ou do VIN B4408747, são utilizados compressores modificados de fábrica. Os compressores da Hella são modificados sem exceção e não apresentam o problema mencionado acima. A tabela ao lado compara os números OE e BHS para efeitos de comparação. Ref. original Ref. BHS GM133956968FK 351 340-241 GM133956948FK 351 340-251 GM133956968FK 351 340-271 GM133956958FK 351 340-361 GM133956938FK 351 340-371 Opel16184258FK 351 340-241 Opel16184238FK 351 340-251 Opel16184258FK 351 340-271 Opel16184248FK 351 340-361 Opel16184258FK 351 340-241 Opel16184228FK 351 340-371 Vauxhall133956968FK 351 340-241 Vauxhall133956948FK 351 340-251 Vauxhall133956968FK 351 340-271 Vauxhall133956958FK 351 340-361 Vauxhall133956968FK 351 340-241 Vauxhall133956938FK 351 340-371

Meriva B

Model year: 2010 - 2012

With air-conditioning system

Loss of oil from the compressor /

Loss of refrigerant

The above-mentioned vehicles can experience a compressor leakage. This is mostly noticeable by escaping oil/dye. To fix this problem, the compressor must be exchanged for a modified version:

Old Part No: Replaced By New Part No:

13 271 264 13 395 696

13 271 266 13 395 693

13 271 267 13 395 694