

# **Opel Mokka — O GPS não funciona | HELLA**

**OpelMokka** Ano de fabrico: 2013 VIN: DB000001–BD033498 O GPS não funciona O símbolo do GPS é exibido riscado no ecrã. Durante a navegação, a atribuição do país pode estar incorreta. Caso sejam exibidas as mensagens de erro supramencionadas, tal pode ser atribuído a uma ligação dos incorrecta na base da antena. Na oficina especializada, a base da antena dos veículos afetados é substituída por uma com cablagem correta. O fabricante do veículo já identificou este problema. Na produção, de acordo com as especificações do fabricante, a partir do VIN: WOLJC7EL2DB033498, são utilizadas bases de antena com cablagem correta.

## **Mokka**

**Model year:** 2013

**Vehicle Identification Number:** DB000001 – BD033498

## **GPS not functioning**

The GPS symbol is crossed out when shown in the display.

There may be incorrect country allocation during navigation.

If the above error messages are displayed, this may be due to incorrect connection of the cable to the aerial base.

The aerial base in the affected vehicles is replaced with a correctly wired base in the specialist workshop.

The vehicle manufacturer has already addressed the issue.

The manufacturer states that correctly wired antenna bases are being used in production from Vehicle Identification Number: WOLJC7EL2DB033498.