

# **Peugeot 307, 308 — Falha da iluminação | HELLA**

**Peugeot 307, 308, Expert** Ano de fabrico: 11.2006–12.2008  
**Falha da iluminação** Apesar de a iluminação estar ligada, pode ocorrer a falha da mesma, nos veículos supracitados. A iluminação não funciona porque o módulo de comando não reconhece o acionamento do interruptor. Para resolver o problema, é realizada uma atualização do software na oficina autorizada. O fabricante automóvel já identificou o problema e realizou uma ação de recolha das viaturas. No entanto, deve ter-se em consideração que, por diversos motivos, nem todos os veículos foram reparados.

**307, 308, Expert**

**Model year:** Nov. 2006 - Dec. 2008

**Lighting failure**

The vehicles mentioned above may experience a lighting failure despite the light being switched on.

The actuation of the switch by the control unit is not detected, so the lighting remains switched off.

This problem can be resolved by performing a software update at the authorized garage.

The vehicle manufacturer has already launched a recall campaign to deal with the problem. For various reasons, however, it must be assumed that not all vehicles have been modified.