

# **Volvo S60 — Sensor da pressão do óleo com defeito | HELLA**

**Volvo S60 Motor: cinco cilindros Ano de fabrico: 2010.06.22–2012.05.14 Sensor da pressão do óleo com defeito** Devido a um sensor da pressão do óleo com defeito, nos veículos supracitados, não é sinalizado nenhum aviso de que o nível do óleo é baixo. Um nível do óleo demasiado baixo pode fazer com que o motor vá abaixo, até mesmo durante a condução (aumentando substancialmente o risco de um acidente). O fabricante do veículo já identificou este problema e informou os proprietários dos veículos afetados. Deve ter-se em consideração que, por diversos motivos, nem todos os veículos foram verificados ou reparados. Na oficina especializada, o erro é resolvido através de uma atualização do software nos veículos afetados.

**S60**

**Engine: five-cylinder**

**Model year: 2010-06-22 - 2012-05-14**

**Defective oil pressure sensor**

Probably due to a defective oil pressure sensor, no warning message is issued when the oil level is low in the above vehicles.

If the oil level is too low, the engine may stall suddenly during driving (this significantly increases the risk of an accident).

The vehicle manufacturer has already addressed the issue and notified the owners of all the affected models.

For various reasons, however, it can be assumed that not all vehicles have been inspected and repaired.

The specialist garage will perform a software update on the affected vehicles in order to remedy the issue.