

Volvo vários modelos — O travão de estacionamento solta-se | HELLA

Volvo S60, S80, V60, V70, XC60 e CX70
Ano de fabrico: 2011–2015
O travão de estacionamento solta-se
Nos veículos acima mencionados, após ligar o motor e engatar uma velocidade, o travão de estacionamento eletrónico pode soltar-se inadvertidamente. O problema pode ocorrer em veículos com sistema Start/Stop e caixa de velocidades manual. A causa deste problema pode ser um erro no software.
Resolução: O fabricante do veículo já identificou este problema e informou os proprietários dos veículos afetados. No entanto, deve ter-se em consideração que nem todos os veículos foram verificados ou reparados.
Aviso de reparação: O software do módulo de comando só pode ser atualizado por um concessionário autorizado.

S60, S80, V60, V70, XC60 and CX70

Model year: 2011 - 2015

Parking brake slips

In the vehicles listed above, the electronic parking brake may release without being operated after the engine is started and the vehicle is put in gear.

This issue may occur in vehicles with a start/stop system and a manual transmission.

This may be caused by faulty software.

Remedy:

The vehicle manufacturer has already addressed the issue and notified the owners of all the affected models.

However, it can be assumed that not all vehicles have been inspected and repaired.

Note for repairs:

The control unit software can only be updated by an authorized dealer.