

VW Tiguan — O ventilador não funciona | HELLA

VWTiguan (5N) Ano de fabrico: a partir de 2007 O ventilador não funciona Nos veículos supramencionados, o ventilador do habitáculo pode congelar quando a temperatura exterior está baixa e, ao mesmo tempo, o tempo está húmido. Em caso de infiltração de humidade (água, neve) no ventilador através do ar exterior, podem ocorrer avarias no sistema de ventilação. Quando o veículo está parado durante um longo período de tempo, a humidade congela e bloqueia o motor do ventilador até “descongelar” novamente. Este processo pode resultar na destruição do regulador do ventilador. Nestes casos, a ventoinha trabalha apenas com a velocidade de rotação máxima. Para resolver o problema, deve proceder-se da seguinte forma: Verificar o ventilador quanto à infiltração de humidade Verificar o regulador do ventilador e, se necessário, substituir Eliminar a infiltração de humidade (o fabricante do veículo utiliza componentes modificados)

V70 III (Type 24) T6

Model year: 2007-2013

Engine: 3.0i V6

With the vehicles specified above, the low pressure service connection of the air-conditioning system cannot be found immediately.

The connection is located on the front passenger side underneath the water tank cover (see figure).

As it is very complicated to remove the cover completely, we recommend that this is raised and locked in place with an appropriate object.