

Opel Vectra C - Battery discharges | HELLA

Opel

Vectra C

All models with electronic

automatic air-conditioning (ECC)

VIN 21000015 - 21031422

Battery discharges

A fault in the control unit for the electronic automatic air-conditioning can be the cause of a discharged battery in some cases. An autonomously changing operating state can result in a permanent current consumption of 75 mA. In this case the software is to be checked using the type plate (Fig.).

If the versions "S3.10" or "S3.12" are found below the bar code, the ECC unit must be replaced.

