



Volvo XC 60 II - replacing the cabin filter


Data sheet	
Manufacturer	Volvo
Vehicle model	XC 60 II
Engine	All models
Year of manufacture	2018 -
Symptoms	Replacing the cabin filter

Important safety note


Cabin/pollen filter change

To change the cabin filter/pollen filter on the vehicles mentioned above, proceed as follows:

- Switch off the ignition
- Move the passenger seat backwards
- Remove the trim in the passenger footwell ([Fig. 1](#))
- Unlock the cover of the filter housing (2x) ([Fig 2.](#))
- Remove the cover downwards
- Pull the filter out downwards ([Fig. 3](#))
- Bend the new filter slightly when installing it and make sure it is installed in the correct position
- Assemble the cover and trim in reverse order



Footwell trim



Locking filter housing



Filter(s)

Reprinting, distribution, reproduction, exploitation in any form or disclosure of the contents of this document, even in part, is prohibited without our express, written approval; indication of the document source is also required. The schematic illustrations, pictures and descriptions serve only for the purposes of explanation and representation of the instructions and cannot be used as a basis for installation or assembly work. All rights reserved.