

Fiat Seicento - Irregular engine running | HELLA

Fiat Seicento

All models with 899ccm engine

Poland plant

Irregular engine running

Irregular engine running

The front right ground cable connection may be faulty if irregular engine running is identified in the above vehicles and there is no entry in the control unit's event memory. Hardening of the insulation material can lead to the cable breaking in the area of the tubular cable lug.

The ground point is located on the right wheel housing behind the headlight in the driving direction.

