

Mercedes Benz Vito 2 - Faulty function: Rear window wiper | HELLA

Mercedes Benz

Type: 639

Model year: from 2003

All models

Faulty function: Rear window wiper

Faulty function: Rear window wiper

Faulty function: Rear window wiper

If one or more of the above problems are identified on this vehicle model, this may be associated with corrosion of the multi-function relay.

