



Fendt Favorit 500 - High/low pressure connections of the air conditioning system


Data sheet

Manufacturer	Fendt
Vehicle model	Favorit 500 (509C - 515C)
Year of manufacture	1993 - 2000
Symptoms	High/low pressure connection of the air conditioning system

Important safety note

Where are the high and low pressure service connections located?

During maintenance and repair work on the air conditioning system, it is necessary to drain or refill the system. However, the service connections are neither in the engine compartment nor on the cabin roof. To access the connections, the cover plate in the area of the right steps ([Fig. 1](#)) must first be removed. High and low pressure connection are now visible. However, the area does not offer much space for connecting the hose lines of the air-conditioning service unit ([Fig. 2](#)).



Reprinting, distribution, reproduction, exploitation in any form or disclosure of the contents of this document, even in part, is prohibited without our express, written approval; indication of the

document source is also required. The schematic illustrations, pictures and descriptions serve only for the purposes of explanation and representation of the instructions and cannot be used as a basis for installation or assembly work. All rights reserved.