



VW Golf 7 - Oil level indicator lamp lights up: Oil loss


Data sheet

Manufacturer	VW
Vehicle model	Golf 7
Engine	1.0i / 1.2i / 1.4i / 1.5i
Year of manufacture	2012 - 2017
Symptoms	Oil level indicator lamp lights up

Important safety note

Oil level indicator lamp lights up: Oil loss

If the engine oil level indicator lamp lights up on the vehicles mentioned above, or if an insufficient oil level or oil loss is detected, the oil lines on the turbocharger may be the cause. Particular attention should be paid to the sealing rings of the lines for the oil supply and oil return. If they can be identified as the cause of the leak, they should be replaced. During assembly, make sure that the new sealing rings are inserted precisely and are not damaged in the process.



Reprinting, distribution, reproduction, exploitation in any form or disclosure of the contents of this document, even in part, is prohibited without our express, written approval; indication of the document source is also required. The schematic illustrations, pictures and descriptions serve only for the purposes of explanation and representation of the instructions and cannot be used as a basis for installation or assembly work. All rights reserved.