

Vauxhall Astra-H - Engine overheats / defective thermostat | HELLA

Vauxhall

Astra-H

Model year: 2009 - 2010

Engine: Z16XEP+Z16XER+Z18XER+A16XER+A18XE

Engine overheats / defective thermostat

The above vehicles can experience engine overheating due to a defective coolant thermostat.

Micro-cracks in the thermostat housing can allow wax filling to escape so that the thermostat no longer opens. In extreme cases, this could lead to engine damage.

Starting with the following

vehicle identification numbers, an improved thermostat has already been installed at the plant by the vehicle manufacturer:

Ellesmere Port plant, VIN: W0L0AHL4898064174

Antwerp plant, VIN: W0L0AHL3595075590

Bochum plant, VIN: W0L0AHL4892123247

Gliwice plant, VIN: W0L0AHM 759G088319