

Vauxhall Meriva B - Loss of oil from the compressor | HELLA

Vauxhall

Meriva B

Model year: 2010 - 2012

With air-conditioning system

Loss of oil from the compressor /

Loss of refrigerant

The above-mentioned vehicles can experience a compressor leakage. This is mostly noticeable by escaping oil/dye. To fix this problem, the compressor must be exchanged for a modified version:

Old Part No: Replaced By New Part No:

13 271 264 13 395 696

13 271 266 13 395 693

13 271 267 13 395 694