

Vauxhall Zafira B - Loss of coolant | HELLA

Vauxhall

Zafira B

Model year: 2005 - 2010

Engine: 1.7 CDTi + 1.9 CDTi

Loss of coolant

In the above vehicles with small charge air coolers (Figure 1), the charge air cooler bracket can rub on the radiator and cause coolant loss (Figure 2).

When installing a new radiator, the charge air cooler bracket must be mounted so that new damage to the radiator can be ruled out.



Figure 2

