

Nissan Pathfinder (R51) - Water Entering the Vehicle Interior | HELLA

Nissan

Pathfinder (R51)

Navara (D40)

Water Entering the Vehicle Interior

Condensation may enter the vehicle interiors of the vehicles listed above.

The cause may be that the condensation drain hose is too short.

The following vehicles are affected:

Pathfinder (R51), up to chassis no.: VSK....R51....345825

Navara (D40), up to chassis no.: VSK....D40....345822

Proceed as follows to rectify the problem:

- Check the condensation drain
- If required, remove the condensation hose and install a modified version (92590-1F700)