

Toyota RAV 4 - Safety belt warning buzzer | HELLA

Toyota

Toyota RAV 4

Model years: 2006 to 2009

Safety belt warning buzzer

If there are complaints for these vehicles that

- <u>with unoccupied front passenger seat</u> -
- <u>with empty front passenger seat</u> -

the safety belt warning light and buzzer are activated, a possible cause is a high sensitivity to the passenger seat occupancy sensor (seat occupancy sensor for the front passenger seat).

Note on corrective action:

- Install revised front passenger seat occupancy sensor (seat occupancy sensor for the front passenger seat).

Spare part:

- Seat occupancy sensor - right-hand steering:
 - 1 unit Spare part no.: 71052-42061
- Seat occupancy sensor - left-hand steering:
 - 1 unit Spare part no.: 71051-42041

The reprinting, distribution, reproduction, exploitation in any form and disclosure of the contents of this document, even in part, is prohibited without our express written approval and indication of the source. The schematic illustrations, figures and descriptions are for explanation and presentation of the document text and cannot be used as a basis for installation or design. All rights reserved.