



VW Golf VII - engine cannot be switched off

Data sheet

Manufacturer	VW
Vehicle model	Golf 7
Engine	All models
Year of manufacture	2012 - 2017
Symptoms	Engine cannot be switched off


Important safety note

Engine continues to run in "ignition position off"

On the vehicles mentioned above, the engine may continue to run even though the ignition starter switch is in the "off" position.

The engine can only be switched off by removing the ignition key. The following codes may be stored in the error memory of the multifunction control unit in connection with short-circuit or ground faults: B12E612 / B12E512 / B11A511.

A defective ignition lock may be causing the problem. To remedy this, the ignition lock should be replaced with a modified version (5Q0905849).



Reprinting, distribution, reproduction, exploitation in any form or disclosure of the contents of this document, even in part, is prohibited without our express, written approval; indication of the document source is also required. The schematic illustrations, pictures and descriptions serve only for the purposes of explanation and representation of the instructions and cannot be used as a basis for installation or assembly work. All rights reserved.