

Mercedes Benz ML 270 CDI - Engine control light is on | HELLA

Mercedes Benz

ML 270 CDI

Model year: 11.1999 - 06.2005

Engine: OM 612,963

Engine control light is on

Vehicle in emergency running mode

Error code: P1189 "intake duct shutdown"

Engine power loss

If one or more of the above problems are identified on this vehicle model, this may be associated with a broken linkage of the charge duct control. In this case, the linkage must be removed and replaced with a spare part modified by the vehicle manufacturer.

Spare parts:

Mounting clip: 611 098 01 26

Linkage: 611 098 02 26

Please follow the installation and removal instructions of the vehicle manufacturer.

