



Nissan Rogue (T32) - Error code P1489 and engine check lamp comes on

Data sheet	
Manufacturer	Nissan
Vehicle model	Rogue (T32)
Engine	1.6 diesel
Year of manufacture	2014 - 2018
Symptoms	Error code P1489 Engine check lamp lights up

Important safety note

A software weakness in the engine control unit of the Nissan Rogue causes the engine check lamp to light up

A software weakness in the engine control unit can cause the engine check lamp to suddenly light up while driving and error code P1489 to be stored in the control unit.

The error can be corrected by means of a software update. Prior to performing the update, electrical and mechanical sources of error should first be excluded. Contacting a Nissan workshop is advisable.

Reprinting, distribution, reproduction, exploitation in any form or disclosure of the contents of this document, even in part, is prohibited without our express, written approval; indication of the document source is also required. The schematic illustrations, pictures and descriptions serve only for the purposes of explanation and representation of the instructions and cannot be used as a basis for installation or assembly work. All rights reserved.