



# Nissan Navara (D40) - Constant coolant loss

## Data sheet

Manufacturer	Nissan
Vehicle model	Navara (D40)
Year of manufacture	2010-2016
Symptoms	Constant loss of coolant

## Important safety note

## Causes of a constant loss of coolant in the Nissan Navara

A steady loss of coolant discovered in the vehicle mentioned above may be caused by cracks in the cylinder head.

The cylinder head should be checked by a specialist company (engine repair) for microcracks in the area of the glow plugs

Before dismantling or replacing the cylinder head, all other possible causes (leaks, cylinder head gasket) should be ruled out.

Reprinting, distribution, reproduction, exploitation in any form or disclosure of the contents of this document, even in part, is prohibited without our express, written approval; indication of the document source is also required. The schematic illustrations, pictures and descriptions serve only for the purposes of explanation and representation of the instructions and cannot be used as a basis for installation or assembly work. All rights reserved.