



Ford Mondeo 2001 Built with parking heater until 06/2002

Parking heater not working, engine cannot be started.

If there are complaints with this vehicle that the parking heater is not working and that the engine cannot be started, one possible cause is a blown fuse. Due to the protection of the power circuit being too low for the parking heater and the injection pump, fuse 23 (15 A) blows, and the above-mentioned faults occur. To eliminate the problem, an additional fuse-protected cable must be laid from the battery to the parking heater and a modified pencil-type heater plug must be inserted in the parking heater. The additional cable must have 20 A fuse protection. It is to be connected directly between the battery and the connection plug on the parking heater. The old power supply cable (pin 1, red cable) in the connection plug for the parking heater must have its pin removed from the connection plug and must be insulated. In order for the modified pencil-type heater plug to be installed the parking heater must be removed.