



## **Skoda Fabia (6Y) Model year: 1999–2006**

### **Blower-motor ballast resistor/ Development of odour in the interior**

If, in the case of the above-mentioned vehicles, the ballast resistor of the interior blower is removed/replaced, it must be ensured that the resistor is fitted in the same position that it was in before removal. If the installation position is incorrect, the resistor may come into contact with the interior filter. Due to the high level of heat development of the resistor, the carrier frame of the interior filter, or the filter itself, may start to char (see photo). This leads to an unbearable odour developing in the vehicle interior. In addition, there is the danger of fire. Please take this into consideration during all work in connection with the blower resistor or the interior filter.

