



Fiat Stilo ***From model year 2000*** ***All models with 1.6 16V engine***

Engine running problems during the warm-up phase.

If there are complaints with these vehicles that engine running problems occur during the warm-up phase, which stop once operating temperature has been reached, one possible cause is the engine control unit. On the basis of the fault symptoms, the impression may be that the MAP sensor should be considered as being the faulty component. If a check of the MAP sensor reveals no fault, and no fault is present in the fault memory either, faulty software in the engine control unit may be the cause. In order to eliminate the fault, the engine control unit software should be updated to the latest version.

Bulletin