Bulletin



© Hella KGaA Hueck & Co., Lippstadt Q4 / 2012 1-1

Isuzu Trooper Models: 1992 to 1998 With automatic transmission:

Starter does not function (Automatic transmission is in [N] neutral).

If there are complaints for the above vehicles that the start does not function or activate (even though the automatic transmission selector is in [N] neutral), a possible cause could be a failure of the automatic transmission lockout switch.

To remedy this problem, check the automatic transmission lockout switch and replace it if necessary.

Automatic transmission lockout switch spare part Number: 1 unit: Spare part no.: 8-96017-178-0



