© HELLA KGaA Hueck & Co., Lippstadt

The reprinting, distribution, reproduction, exploitation in any form and disclosure of the contents of this document, even in part, is prohibited without our express written approval and indication of the source. The schematic illustrations, pictures and descriptions are for explanation and presentation of the document text and cannot be used as a basis for installation or design. All rights reserved.

## BULLETIN

## Nissan Micra (K13)/Note (E12) Year of construction: 07/2015 – 01/2016 Engine: 1.2 DIG-S (HR12DDR)

## Engine stalls during driving

In the vehicles listed above, there have been complaints of the engine stalling during driving and refusing to start again.

In this case, the aforementioned problem may be caused by a short circuit in the ignition coil.

The short circuit can damage the fuses and cause them to fail, which can cause the engine to stall and prevent it from being started again.

## Repair note:

The vehicle manufacturer has already addressed the issue and notified the owners of all the affected models. However, it can be assumed that not all vehicles have been inspected and repaired.

Specialist garages will install new ignition coils in the affected vehicles.





