Bulletin



© Hella KGaA Hueck & Co., Lippstadt

20. Dezember 2005

- . . 1

Opel Corsa C, Corsa C Combo All models and engines

Parking light not working.

If there are complaints with these vehicles that the parking light cannot be switched on using the indicator lever, this is not a faulty function.

With these vehicles it is no longer possible to switch the parking light on by moving the indicator lever into the upper or lower position with the key removed from the ignition. But if the indicator lever is in the upper or lower position when the driver door is opened, the warning buzzer sounds. It is not possible to reprogram the vehicle in order to switch the warning buzzer off or the parking light function on.

Bulletin

