



Udvidelser og ændringer i softwareversion 67

Funktioner oplistet efter producent

Denne liste giver kun et overordnet overblik over dataudvidelserne i forbindelse med den nyeste opdatering. En komplet liste over samtlige modeludvidelser for hver af producenterne ville i denne sammenhæng være alt for omfattende.

Udvidede og reviderede producenter

Aprilia

Fejlkode	(SR, SR GT 125), (SR, SR GT 200), (Tuareg, Tuareg 660 E5), (Tuono, Tuono 660 Factory E5)
Parameter	(SR, SR GT 125), (SR, SR GT 200), (Tuareg, Tuareg 660 E5), (Tuono, Tuono 660 Factory E5)
Aktuatorrest	(SR, SR GT 125), (SR, SR GT 200), (Tuareg, Tuareg 660 E5), (Tuono, Tuono 660 Factory E5)
Grundindstilling	Nulstilling af indlæringsværdier ((Tuareg, Tuareg 660 E5), (SR, SR GT 125), (SR, SR GT 200), (Tuono, Tuono 660 Factory E5)) Udluftning af ABS-hydraulikenhed bag ((Tuareg, Tuareg 660 E5), (Tuono, Tuono 660 Factory E5)) Initialisering af motorstyreenhed ((Tuareg, Tuareg 660 E5), (Tuono, Tuono 660 Factory E5)) Udluftning af ABS-hydraulikenhed for ((Tuareg, Tuareg 660 E5), (Tuono, Tuono 660 Factory E5))
Kodning	
Servicenulstilling	(RS, RS 660 E5), (RSV, RSV 4 1000 RF), (RSV, RSV 4 1000 RR), (RSV, RSV 4 1100 Factory), (RSV, RSV 4 1100 RR), (Shiver, Shiver SL 900), (Shiver, Shiver SL 900 Navi), (Tuareg, Tuareg 660 E5), (Tuono, Tuono 1100 Factory), (Tuono, Tuono 1100 RR), (Tuono, Tuono 660 E5), (Tuono, Tuono 660 Factory E5)

DoIP/CANDoIP/CAN	
kan kun diagnosticeres med mega macs X	
kan diagnosticeres med mega macs X	

Cyber Security Management (CSM)	Cyber Security Management (CSM)
kan kun diagnosticeres med Cyber Security Management	kan kun diagnosticeres med Cyber Security Management



Motorcykel-diagnose

BMW

Fejlkode	(None, CE04)
Parameter	(None, CE04)
Aktuator-test	(None, CE04)
Grundindstilling	Initialisering af undervogn ((K 1600, K 1600 GT)) Udluftning af ABS-hydraulikenhed bag ((None, CE04)) Udluftning af ABS-hydraulikenhed for ((None, CE04))
Kodning	
Servicenulstilling	(S 1000, S 1000 XR)

| DoIP/CANDoIP/CAN
| kan kun diagnosticeres med mega macs X
| kan diagnosticeres med mega macs X

| Cyber Security Management (CSM)
| Cyber Security Management (CSM)

| kan kun diagnosticeres med Cyber Security Management
| kan diagnosticeres med Cyber Security Management

Brough Superior

Fejlkode	(Lawrence, Lawrence SS1MKL), (Pendine, Pendine Sand Racer), (SS100, SS100 MK2)
Parameter	(Lawrence, Lawrence SS1MKL), (Pendine, Pendine Sand Racer), (SS100, SS100 MK2)
Aktuator-test	(Lawrence, Lawrence SS1MKL), (Pendine, Pendine Sand Racer), (SS100, SS100 MK2)
Grundindstilling	
Kodning	
Servicenulstilling	



Motorcykel-diagnose

- | DoIP/CANDoIP/CAN
 - | kan kun diagnosticeres med mega macs X
 - | kan diagnosticeres med mega macs X
-

- | Cyber Security Management (CSM)
- | Cyber Security Management (CSM)
- | kan kun diagnosticeres med Cyber Security Management
- | kan diagnosticeres med Cyber Security Management

CFMOTO

- | Fejlkode (400, 400 GT), (650, 650 GT), (700, 700 CL-X Heritage)
 - | Parameter (400, 400 GT), (650, 650 GT), (700, 700 CL-X Heritage)
 - | Aktuatorstest (400, 400 GT), (650, 650 GT)
 - | Grundindstilling
 - | Kodning
 - | Servicenulstilling
-

- | DoIP/CANDoIP/CAN
 - | kan kun diagnosticeres med mega macs X
 - | kan diagnosticeres med mega macs X
-

- | Cyber Security Management (CSM)
- | Cyber Security Management (CSM)
- | kan kun diagnosticeres med Cyber Security Management
- | kan diagnosticeres med Cyber Security Management



Motorcykel-diagnose

Ducati

| Fejlkode

(Desert, Desert X), (Diavel, Diavel 1260 E5), (Diavel, X Diavel), (Diavel, X Diavel 1260), (Diavel, X Diavel E5), (Hypermotard, 950 Hypermotard E5), (Hypermotard, Hypermotard 950 SP), (Monster, M 1200 R), (Monster, M 797), (Monster, Monster), (Multistrada, MTS 950), (Multistrada, MTS 950 E5), (Multistrada, MTS 950 S), (Multistrada, MTS 950 S E5), (Multistrada, MTS V2), (Multistrada, MTS V2 E5), (Multistrada, MTS V2 S), (Multistrada, MTS V2 S E5), (Multistrada, MTS V4), (Multistrada, MTS V4 S), (Scrambler, Scrambler 800), (Scrambler, Scrambler 800 E5), (Scrambler, Scrambler Cafe Racer E3), (Scrambler, Scrambler Cafe Racer E4), (Scrambler, Scrambler Desert Sled), (Scrambler, Scrambler Desert Sled E4), (Scrambler, Scrambler Desert Sled E5), (Scrambler, Scrambler Sixty2), (Scrambler, Scrambler Urban E4), (Scrambler, Scrambler Urban E5), (Streetfighter, Streetfighter 848), (Streetfighter, Streetfighter V2), (Streetfighter, Streetfighter V4 E5), (Superbike, Panigale V4), (Superbike, Panigale V4 E5), (SuperSport, 939), (SuperSport, 950)

| Parameter

(Desert, Desert X), (Diavel, Diavel 1260 E5), (Diavel, X Diavel), (Diavel, X Diavel 1260), (Diavel, X Diavel E5), (Hypermotard, 950 Hypermotard E5), (Hypermotard, Hypermotard 950 SP), (Monster, M 1200 R), (Monster, M 797), (Monster, Monster), (Multistrada, MTS 950), (Multistrada, MTS 950 E5), (Multistrada, MTS 950 S), (Multistrada, MTS 950 S E5), (Multistrada, MTS V2), (Multistrada, MTS V2 E5), (Multistrada, MTS V2 S), (Multistrada, MTS V2 S E5), (Multistrada, MTS V4), (Multistrada, MTS V4 S), (Scrambler, Scrambler 800), (Scrambler, Scrambler 800 E5), (Scrambler, Scrambler Cafe Racer E3), (Scrambler, Scrambler Cafe Racer E4), (Scrambler, Scrambler Desert Sled), (Scrambler, Scrambler Desert Sled E4), (Scrambler, Scrambler Desert Sled E5), (Scrambler, Scrambler Sixty2), (Scrambler, Scrambler Urban E4), (Scrambler, Scrambler Urban E5), (Streetfighter, Streetfighter 848), (Streetfighter, Streetfighter V2), (Streetfighter, Streetfighter V4 E5), (Superbike, Panigale V4), (Superbike, Panigale V4 E5), (SuperSport, 939), (SuperSport, 950)

| Aktuatortest

(Desert, Desert X), (Diavel, Diavel 1260 E5), (Diavel, X Diavel), (Diavel, X Diavel 1260), (Diavel, X Diavel E5), (Hypermotard, 950 Hypermotard E5), (Hypermotard, Hypermotard 950 SP), (Monster, M 1200 R), (Monster, M 797), (Monster, Monster), (Multistrada, MTS 950), (Multistrada, MTS 950 E5), (Multistrada, MTS 950 S), (Multistrada, MTS 950 S E5), (Multistrada, MTS V2), (Multistrada, MTS V2 E5), (Multistrada, MTS V2 S), (Multistrada, MTS V2 S E5), (Multistrada, MTS V4), (Multistrada, MTS V4 S), (Scrambler, Scrambler 800), (Scrambler, Scrambler 800 E5), (Scrambler, Scrambler Cafe Racer E3), (Scrambler, Scrambler Cafe Racer E4), (Scrambler, Scrambler Desert Sled), (Scrambler, Scrambler Desert Sled E4), (Scrambler, Scrambler Desert Sled E5), (Scrambler, Scrambler Sixty2), (Scrambler, Scrambler Urban E4), (Scrambler, Scrambler Urban E5), (Streetfighter, Streetfighter 848), (Streetfighter, Streetfighter V2), (Streetfighter, Streetfighter V4 E5), (Superbike, Panigale V4), (Superbike, Panigale V4 E5), (SuperSport, 939), (SuperSport, 950)

| Grundindstilling

Initialisering af rotationshastighedssensor ((Multistrada, MTS V4), (Multistrada, MTS V4 S))

Nulstilling af lærte værdier for brændstofsystem ((Desert, Desert X), (Diavel, Diavel 1260 E5), (Diavel, X Diavel 1260), (Diavel, X Diavel), (Diavel, X Diavel E5), (Multistrada, MTS 950 E5), (Multistrada, MTS 950 S E5), (Multistrada, MTS V2), (Multistrada, MTS V2 E5), (Multistrada, MTS V2 S), (Multistrada, MTS V2 S E5), (Multistrada, MTS V4), (Multistrada, MTS V4 S), (SuperSport, 939), (SuperSport, 950))

Nulstilling af lærte værdier for lambdasonde ((Scrambler, Scrambler Cafe Racer E4), (Multistrada, MTS 950 S), (Scrambler, Scrambler Sixty2), (Desert, Desert X), (Monster, Monster), (Multistrada, MTS 950), (Multistrada, MTS 950 E5), (Multistrada, MTS 950 S E5), (Multistrada, MTS V2), (Multistrada, MTS V2 E5), (Multistrada, MTS V2 S), (Multistrada, MTS V2 S E5), (Scrambler, Scrambler 800), (Scrambler, Scrambler Cafe Racer E3), (Scrambler, Scrambler Desert Sled), (Scrambler, Scrambler Desert Sled E4), (Scrambler, Scrambler Urban E4), (SuperSport, 939))



Motorcykel-diagnose

Nulstilling af lærte værdier for gasspjæld ((Diavel, Diavel 1260 E5), (Diavel, X Diavel 1260), (Diavel, X Diavel), (Diavel, X Diavel E5), (Monster, M 797))

Nulstilling af indlæringsværdier motor ((Streetfighter, Streetfighter 848), (Monster, M 797))

Udskift batteri ((Desert, Desert X), (Diavel, Diavel 1260 E5), (Diavel, X Diavel 1260), (Diavel, X Diavel), (Diavel, X Diavel E5), (Hypermotard, 950 Hypermotard E5), (Multistrada, MTS 950 E5), (Multistrada, MTS 950 S E5), (Multistrada, MTS V2), (Multistrada, MTS V2 E5), (Multistrada, MTS V2 S), (Multistrada, MTS V2 S E5), (Multistrada, MTS V4), (Multistrada, MTS V4 S), (Streetfighter, Streetfighter V2), (Streetfighter, Streetfighter V4 E5), (SuperSport, 939), (SuperSport, 950), (Superbike, Panigale V4), (Superbike, Panigale V4 E5))

Kørsel til monteringsposition for udstødningsspjældmotor ((Multistrada, MTS V2), (Multistrada, MTS V2 E5), (Multistrada, MTS V2 S), (Multistrada, MTS V2 S E5), (SuperSport, 950))

Indlæring af gasspjæld ((Streetfighter, Streetfighter 848), (Scrambler, Scrambler Cafe Racer E4), (Multistrada, MTS 950 S), (Scrambler, Scrambler Sixty2), (Desert, Desert X), (Monster, Monster), (Multistrada, MTS 950), (Multistrada, MTS 950 E5), (Multistrada, MTS 950 S E5), (Multistrada, MTS V2), (Multistrada, MTS V2 E5), (Multistrada, MTS V2 S), (Multistrada, MTS V2 S E5), (Scrambler, Scrambler 800), (Scrambler, Scrambler Cafe Racer E3), (Scrambler, Scrambler Desert Sled), (Scrambler, Scrambler Desert Sled E4), (Scrambler, Scrambler Urban E4), (SuperSport, 939))

| Kodning

Aktivering/deaktivering af skifteautomat ((Multistrada, MTS 950 S), (Hypermotard, 950 Hypermotard E5), (Monster, Monster), (Multistrada, MTS 950), (Multistrada, MTS 950 E5), (Multistrada, MTS 950 S E5), (Streetfighter, Streetfighter V2), (Streetfighter, Streetfighter V4 E5), (SuperSport, 950), (Superbike, Panigale V4), (Superbike, Panigale V4 E5))

Deaktivering/aktivering af tyverialarm ((Multistrada, MTS 950 S), (Diavel, Diavel 1260 E5), (Diavel, X Diavel 1260), (Diavel, X Diavel), (Diavel, X Diavel E5), (Hypermotard, 950 Hypermotard E5), (Monster, Monster), (Monster, M 1200 R), (Monster, M 797), (Multistrada, MTS 950), (Multistrada, MTS 950 E5), (Multistrada, MTS 950 S E5), (Streetfighter, Streetfighter V2), (Streetfighter, Streetfighter V4 E5), (SuperSport, 939), (SuperSport, 950), (Superbike, Panigale V4), (Superbike, Panigale V4 E5))

De-/aktivering af kørelys ((Scrambler, Scrambler Cafe Racer E4), (Scrambler, Scrambler Sixty2), (Diavel, Diavel 1260 E5), (Diavel, X Diavel 1260), (Diavel, X Diavel), (Diavel, X Diavel E5), (Hypermotard, 950 Hypermotard E5), (Monster, Monster), (Scrambler, Scrambler 800), (Scrambler, Scrambler Cafe Racer E3), (Scrambler, Scrambler Desert Sled), (Scrambler, Scrambler Desert Sled E4), (Scrambler, Scrambler Urban E4), (Streetfighter, Streetfighter V2), (Streetfighter, Streetfighter V4 E5), (SuperSport, 939), (SuperSport, 950), (Superbike, Panigale V4), (Superbike, Panigale V4 E5))

Deaktivering/aktivering af varmegreb ((Multistrada, MTS 950 S), (Diavel, Diavel 1260 E5), (Diavel, X Diavel 1260), (Diavel, X Diavel), (Diavel, X Diavel E5), (Hypermotard, 950 Hypermotard E5), (Monster, Monster), (Monster, M 797), (Multistrada, MTS 950), (Multistrada, MTS 950 E5), (Multistrada, MTS 950 S E5), (Streetfighter, Streetfighter V2), (Streetfighter, Streetfighter V4 E5), (SuperSport, 939), (SuperSport, 950), (Superbike, Panigale V4), (Superbike, Panigale V4 E5))

| Servicenulstilling

((Desert, Desert X), (Diavel, Diavel 1260), (Diavel, Diavel 1260 E5), (Diavel, X Diavel), (Diavel, X Diavel 1260), (Diavel, X Diavel E5), (Hypermotard, 950 Hypermotard E5), (Hypermotard, Hypermotard 950 SP), (Monster, M 1200 E4), (Monster, M 1200 R), (Monster, M 797), (Monster, M 821 E4), (Monster, Monster), (Multistrada, MTS 1200), (Multistrada, MTS 1260 S), (Multistrada, MTS 950), (Multistrada, MTS 950 E5), (Multistrada, MTS 950 S), (Multistrada, MTS 950 S E5), (Multistrada, MTS V2), (Multistrada, MTS V2 E5), (Multistrada, MTS V2 S), (Multistrada, MTS V2 S E5), (Multistrada, MTS V4), (Multistrada, MTS V4 S), (Scrambler, Scrambler 1100), (Scrambler, Scrambler 1100 Sport), (Scrambler, Scrambler 800), (Scrambler, Scrambler 800 E5), (Scrambler, Scrambler Cafe Racer E3), (Scrambler,



Motorcykel-diagnose

Scrambler Cafe Racer E4), (Scrambler, Scrambler Desert Sled), (Scrambler, Scrambler Desert Sled E4), (Scrambler, Scrambler Desert Sled E5), (Scrambler, Scrambler Sixty2), (Scrambler, Scrambler Urban E4), (Scrambler, Scrambler Urban E5), (Streetfighter, Streetfighter 848), (Streetfighter, Streetfighter V2), (Streetfighter, Streetfighter V4), (Streetfighter, Streetfighter V4 E5), (Superbike, Panigale V2), (Superbike, Panigale V4), (Superbike, Panigale V4 E5), (SuperSport, 939), (SuperSport, 950)

DoIP/CANDoIP/CAN

kan kun diagnosticeres med mega macs X
kan diagnosticeres med mega macs X

Cyber Security Management (CSM) Cyber Security Management (CSM)

kan kun diagnosticeres med Cyber Security Management
kan kun diagnosticeres med Cyber Security Management

Kawasaki

- Fejlkode (ZX, ZX-10 R)
- Parameter (ZX, ZX-10 R)
- Aktuator-test (ZX, ZX-10 R)
- Grundindstilling Nulstilling af lærte værdier for tomgangsregulator ((ZX, ZX-10 R))
- Kodning
- Servicenustilling



Motorcykel-diagnose

DoIP/CANDoIP/CAN

kan kun diagnosticeres med mega macs X
kan diagnosticeres med mega macs X

Cyber Security Management (CSM) Cyber Security Management (CSM)

kan kun diagnosticeres med Cyber Security Management
kan kun diagnosticeres med Cyber Security Management

KTM

Fejlkode (250, 250 TPI EXC-F), (250, 250 TPI XC-W), (300, 300 TPI EXC-F), (300, 300 TPI XC-W)

Parameter (250, 250 TPI EXC-F), (250, 250 TPI XC-W), (300, 300 TPI EXC-F), (300, 300 TPI XC-W)

Aktuator test (250, 250 TPI EXC-F), (250, 250 TPI XC-W), (300, 300 TPI EXC-F), (300, 300 TPI XC-W)

Grundindstilling Forfyld oliepumpe ((250, 250 TPI XC-W), (300, 300 TPI XC-W), (300, 300 TPI EXC-F), (250, 250 TPI EXC-F))

Nulstilling af indlæringsværdier motor ((250, 250 TPI XC-W), (300, 300 TPI XC-W), (300, 300 TPI EXC-F), (250, 250 TPI EXC-F))

Kodning

Servicenustilling (790, 790 Adventure), (790, 790 Duke)

DoIP/CANDoIP/CAN

kan kun diagnosticeres med mega macs X
kan diagnosticeres med mega macs X

Cyber Security Management (CSM) Cyber Security Management (CSM)

kan kun diagnosticeres med Cyber Security Management
kan kun diagnosticeres med Cyber Security Management



Motorcykel-diagnose

Kymco

- | Fejlkode (AK, AK 550i)
- | Parameter (AK, AK 550i)
- | Aktuatorrest
- | Grundindstilling
Udluftning af ABS-hydraulikenhed bag ((AK, AK 550i))
Udluftning af ABS-hydraulikenhed for ((AK, AK 550i))
- | Kodning
- | Servicenulstilling

- | DoIP/CANDoIP/CAN
- | kan kun diagnosticeres med mega macs X
kan diagnosticeres med mega macs X

- | Cyber Security Management (CSM)
Cyber Security Management (CSM)
- | kan kun diagnosticeres med Cyber Security Management
kan diagnosticeres med Cyber Security Management

Macbor

- | Fejlkode (Montana, Montana XR1), (Montana, Montana XR3), (Montana, Montana XR5), (Rockster, Rockster), (Rockster, Rockster Flat), (Shifter, Shifter MC1), (Stormer, Stormer R)
- | Parameter (Montana, Montana XR1), (Montana, Montana XR3), (Montana, Montana XR5), (Rockster, Rockster), (Rockster, Rockster Flat), (Shifter, Shifter MC1), (Stormer, Stormer R)
- | Aktuatorrest (Montana, Montana XR5)
- | Grundindstilling
- | Kodning
- | Servicenulstilling



Motorcykel-diagnose

DoIP/CANDoIP/CAN

kan kun diagnosticeres med mega macs X
kun diagnosticeres med mega macs X

Cyber Security Management (CSM) Cyber Security Management (CSM)

kan kun diagnosticeres med Cyber Security Management
kan kun diagnosticeres med Cyber Security Management

Moto Guzzi

Fejlkode

Parameter

Aktuatorrest

Grundindstilling

Kodning

Servicenulstilling

(V7, V7 750 III), (V7, V7 850 Spezial E5), (V7, V7 850 Stone E5), (V9, V9 850 Bobber), (V9, V9 850 Bobber E5), (V9, V9 850 Roamer), (V9, V9 850 Roamer E5)

DoIP/CANDoIP/CAN

kan kun diagnosticeres med mega macs X
kun diagnosticeres med mega macs X

Cyber Security Management (CSM) Cyber Security Management (CSM)

kan kun diagnosticeres med Cyber Security Management
kan kun diagnosticeres med Cyber Security Management



Motorcykel-diagnose

Peugeot

| Fejlkode (Django, Django 125), (Metropolis, Metropolis 400), (Speedfight, Speedfight 4 50)

| Parameter (Django, Django 125), (Metropolis, Metropolis 400), (Speedfight, Speedfight 4 50)

| Aktuatortest (Django, Django 125), (Speedfight, Speedfight 4 50)

| Grundindstilling

| Kodning

| Servicenulstilling

| DoIP/CANDoIP/CAN

| kan kun diagnosticeres med mega macs X
kan diagnosticeres med mega macs X

| Cyber Security Management (CSM)
Cyber Security Management (CSM)

| kan kun diagnosticeres med Cyber Security Management
kan diagnosticeres med Cyber Security Management

Piaggio

| Fejlkode (MP 3, MP 3 350 DRL), (MP 3, MP 3 500 E4)

| Parameter (MP 3, MP 3 350 DRL), (MP 3, MP 3 500 E4)

| Aktuatortest (MP 3, MP 3 350 DRL), (MP 3, MP 3 500 E4)

| Grundindstilling
Nulstilling af lærte værdier for gasspjæld ((MP 3, MP 3 350 DRL))
Nulstilling af indlæringsværdier motor ((MP 3, MP 3 350 DRL))
Udluftning af ABS-hydraulikenhed ((MP 3, MP 3 500 E4), (MP 3, MP 3 350 DRL))

| Kodning

| Servicenulstilling



Motorcykel-diagnose

- | DoIP/CANDoIP/CAN
 - | kan kun diagnosticeres med mega macs X
 - | kan diagnosticeres med mega macs X
-

- | Cyber Security Management (CSM)
- | Cyber Security Management (CSM)
- | kan kun diagnosticeres med Cyber Security Management
- | kan diagnosticeres med Cyber Security Management

Royal Alloy

- | Fejlkode (GP, GP 200 S), (GP, GP 300 S), (TG, TG 200 S), (TG, TG 300 S)
 - | Parameter (GP, GP 200 S), (GP, GP 300 S), (TG, TG 200 S), (TG, TG 300 S)
 - | Aktuatorrest (GP, GP 200 S), (GP, GP 300 S), (TG, TG 200 S), (TG, TG 300 S)
 - | Grundindstilling
 - | Kodning
 - | Servicenulstilling
-

- | DoIP/CANDoIP/CAN
 - | kan kun diagnosticeres med mega macs X
 - | kan diagnosticeres med mega macs X
-

- | Cyber Security Management (CSM)
- | Cyber Security Management (CSM)
- | kan kun diagnosticeres med Cyber Security Management
- | kan diagnosticeres med Cyber Security Management



Motorcykel-diagnose

Vespa

| Fejlkode

| Parameter

| Aktuatortest

| Grundindstilling

| Kodning

| Servicenulstilling

(GTS, GTS 125 Supertech), (GTS, GTS 125 Supertech E5), (GTS, GTS 300 Supertech), (GTS, GTS 300 Supertech E5), (Primavera, Primavera 125 E4), (Primavera, Primavera 125 E5), (Primavera, Primavera 150 E5), (S / SXL / Sprint, Sprint 125 E4), (S / SXL / Sprint, Sprint 125 E5), (S / SXL / Sprint, Sprint 150 E4), (S / SXL / Sprint, Sprint 150 E5)

| DoIP/CANDoIP/CAN

| kan kun diagnosticeres med mega macs X
kan diagnosticeres med mega macs X

| Cyber Security Management (CSM)
Cyber Security Management (CSM)

| kan kun diagnosticeres med Cyber Security Management
kan kun diagnosticeres med Cyber Security Management

Voge

| Fejlkode

(Brivido, Brivido 300), (Brivido, Brivido 300 E5), (Brivido, Brivido 500 R), (Brivido, Brivido 500 R E5), (Trofeo, Trofeo 300 AC), (Trofeo, Trofeo 300 AC E5), (Trofeo, Trofeo 300 ACX Scrambler E5), (Valico, Valico 500 DS), (Valico, Valico 500 DS E5)

| Parameter

(Brivido, Brivido 300), (Brivido, Brivido 300 E5), (Brivido, Brivido 500 R), (Brivido, Brivido 500 R E5), (Trofeo, Trofeo 300 AC), (Trofeo, Trofeo 300 AC E5), (Trofeo, Trofeo 300 ACX Scrambler E5), (Valico, Valico 500 DS), (Valico, Valico 500 DS E5)

| Aktuatortest

(Brivido, Brivido 300), (Brivido, Brivido 300 E5), (Brivido, Brivido 500 R), (Brivido, Brivido 500 R E5), (Trofeo, Trofeo 300 AC), (Trofeo, Trofeo 300 AC E5), (Trofeo, Trofeo 300 ACX Scrambler E5), (Valico, Valico 500 DS), (Valico, Valico 500 DS E5)

| Grundindstilling

| Kodning



Motorcykel-diagnose

| Servicenulstilling

| DoIP/CANDoIP/CAN

kan kun diagnosticeres med mega macs X
kan kun diagnosticeres med mega macs X

| Cyber Security Management (CSM) Cyber Security Management (CSM)

kan kun diagnosticeres med Cyber Security Management
kan kun diagnosticeres med Cyber Security Management

Yamaha

| Fejlkode (X-Max, X-Max 125 E5), (XSR, XSR 700 E5), (XT, XT-1200 Z)

| Parameter (X-Max, X-Max 125 E5), (XSR, XSR 700 E5)

| Aktuator-test (X-Max, X-Max 125 E5), (XSR, XSR 700 E5)

| Grundindstilling Nulstilling af lærte værdier for tomgangsregulator ((X-Max, X-Max 125 E5), (XSR, XSR 700 E5))

Nulstilling af indlæringsværdier motor ((X-Max, X-Max 125 E5), (XSR, XSR 700 E5))

Udluftning af ABS-hydraulikenhed ((X-Max, X-Max 125 E5), (XSR, XSR 700 E5))

| Kodning

| Servicenulstilling



Motorcykel-diagnose

- | DoIP/CANDoIP/CAN
 - | kan kun diagnosticeres med mega macs X
 - | kan diagnosticeres med mega macs X
-

- | Cyber Security Management (CSM)
- | Cyber Security Management (CSM)
- | kan kun diagnosticeres med Cyber Security Management
- | kan diagnosticeres med Cyber Security Management