

Audi Q5 - Baklys virker periodisk ikke | HELLA

AudiQ5Årgang: 09/2015 - 05/2017Baklys virker periodisk ikkeHvis ovenstående fejl konstateres på ovennævnte model, kan det skyldes en funktionsfejl i baklyskontakten.Denne funktionsfejl kan desuden medfører forstyrrelser i parkeringshjælp-systemet og/eller bakkameraet.Modeller med 6-trins manuelt gear er berørt.Problemet optræder periodisk ved lave udetemperaturer.Bemærk:- Der lyder ikke nogen signaltone, når der skiftes til bakgear.ReparationsanvisningKontroller baklyskontakten, og udskift den evt. med en forbedret udførelse.

Q5

Model years: 09/2015 – 05/2017

Reversing light sporadically not functioning

If the indicated problem occurs in above vehicle, a malfunction of the reversing light switch might be a possible cause.

This malfunction might additional cause defects of the parking assist system and/or rear view camera system.

Vehicles with six-speed gearboxes are affected.

Complaints occur sporadically during cold exterior temperatures.

Please note:

- No acoustic signal occurs when engaging reverse gear.

Repair notes

Check reversing light switch and replace with improved version, where necessary.