

Citroën Berlingo - Multifunktionsenheden virker ikke | HELLA

Citroën Citroën Berlingo Årgang: 2005 - 2011 Multifunktionsenheden virker ikke
Hornet virker ikkeI ovennævnte modeller kan det forekomme, at multifunktionsstyreenheden ikke virker, og/eller at hornet ikke virker. En mulig årsag til fejlen kan i nogle biler være en defekt i ledningerne til bremsepedalkontakten, idet de ved en uheldig placering kan gnave mod ratakslen. Afhjælpning sker ved at kontrollere ledningerne og reparere beskadiget isolering af ledningerne med et reparationssæt. Desuden skal der påsættes en passende beskyttelseskappe, og ledningsbundtet skal fastgøres igen. Evt. skal ledningsbundtet udskiftes, hvilket dog er en ganske omfattende opgave. Derpå foretages en funktionskontrol.

Citroen Berlingo

Model years: 2005 - 2011

In the above vehicle, the multi-function control unit and/or or the signal horn may malfunction. One possible cause in some vehicles may be a defect in the wiring harness of the brake pedal switch that can scrub at the steering shaft due to unfavourable positioning.

As a corrective action, the wiring harness should be checked, and damaged cable insulations should be repaired with a repair kit. In addition, pull a suitable protective cover onto the wiring and fasten the harness again.

If necessary, the harness must be replaced, although this is associated with a significant amount of work.

Finally perform a functional test.