

Citroën C2 / C3 Pluriel - Forlygter virker ikke | HELLA

Citroën C2 / C3 / C3 Pluriel Årgang: 10/2006 - 03/2008 Forlygter virker ikke For ovennævnte modeller klages der over, at forlygterne ikke virker. Årsagen til dette problem i lygtesystemet kan være en fejlagtig styreenheds-software. Lyskontaktens stilling registreres muligvis ikke af styreenheden, hvilket medfører, at forlygterne ikke virker. Bilfabrikanten har allerede taget sig af problemet, og brugerne af de berørte biler er underrettet. Man må dog af diverse grunde gå ud fra, at ikke alle biler er blevet kontrolleret eller udbedret. Problemet afhjælpes ved, at værkstedet foretager en software-opdatering af de berørte biler.

C2 / C3 / C3 Pluriel

Model year: 10/2006 – 03/2008

Failure of the front light

The complaint has been made that the front headlight fails in the above vehicles.

The above problem with the lighting system may be caused by faulty ECU software.

The light switch position may not be detected by the ECU and thus leads to a failure of the front lighting.

The vehicle manufacturer has already addressed the issue and notified the owners of all the affected models. For various reasons, however, it must be assumed that not all vehicles have been checked or modified.

To remedy the above problem, the software needs to be updated at the relevant vehicles by a specialist workshop.