

Dacia Sandero - Failure of the ABS warning lamp | HELLA

Dacia

Sandero

Model year: May 2008 - January 2008

Failure of the ABS warning lamp

The ABS warning lamp may fail in the above vehicles.



The ABS warning lamp may fail in the above vehicles.