

Fiat Ducato - Nedsat motoreffekt / motorkontrollampe lyser | HELLA

FiatDucatoÅrgang: 01/2015 - 01/2018Motor: MultijetNedsat motoreffekt / motorkontrollampen lyserPå ovennævnte modeller kan ladeluftkølerens studs løsne sig fra tilslutningshuset. Det medfører betydeligt nedsat motoreffekt, og at motorkontrollampen lyser. For at afhjælpe fejlen skal fastgørelsen af studsene kontrolleres, og holdeklemmen skal udskiftes med en ændret udførelse. Bilfabrikanten har allerede taget sig af problemet, og brugerne af de berørte biler er underrettede. Af en række årsager må man dog gå ud fra, at ændringerne ikke er udført på alle køretøjer.

Ducato

Model years: 01/2015 - 01/2018

Engine: Multijet

Power loss / Engine warning light illuminates

In above vehicle, the fitting of the intercooler might disconnect from connecting body.

This results in a significant engine power loss and the engine indicator lamp will light up.

To remedy the situation, check the respective fixing of the fitting and replace the holding clamp against a modified version.

The vehicle manufacturer has already addressed the issue and notified the owners of the affected models. Due to various reasons, we must assume that not all vehicles have undergone the retrofitting/ modification.