

Fiat Idea / Lancia Musa - Katastrofeblinket tænder uden at være blevet aktiveret | HELLA

Fiat

Idea / Lancia Musa

Årgang 2003 -2007

Alle modeller med manuel temperaturregulering

Katastrofeblinket tænder uden at være blevet aktiveret

Hvis der klages over problemet med, at katastrofeblinket tænder af sig selv i de ovennævnte køretøjer, kan problemet skyldes en defekt katastrofeblinkkontakt.



Fig. 1



Reparationsvejledning:

ⓘ Important safety notice

The following technical information and tips for practical use have been set up by HELLA in order to offer professional support to automotive workshops in their daily work. The information available here on this website is only to be used by appropriately trained specialist staff.

The reprinting, distribution, reproduction, exploitation in any form and disclosure of the contents of this document, even in part, is prohibited without our express written approval and indication of the source. The schematic illustrations, figures and descriptions are for explanation and presentation of the document text and cannot be used as a basis for installation or design. All rights reserved.