

# Kia Rio, forskellige modeller - Motorkontrollampen lyser | HELLA

**Kia Picanto Alle med benzinmotor årgang**

**01/2005 Motorkontrollampen lyser Hvis kunden klager over fejlen**

**- motorkontrollampen lyser - kan der evt. være lagt fejlkode**

**P0030 (opvarmet lambdasonde1, cylinderrække1, funktionsfejl**

**i varmereguleringens kredsløb). Årsagen kan være en dårlig**

**fabrikationskvalitet af lodningerne i ledningsnettet. Mulige årsager:-**

**Brud hhv. for stor modstand i ledningsnettet til den opvarmede**

**lambdasonde.- Brud hhv. for stor modstand i ledningsnettet til**

**tryksensoren i indsugningsmanifolden. Afhjælpning:- Kontroller**

**lodningerne i ledningsnettet.- Reparer ledningsnettet om**

**nødvendigt.**

**Picanto**

**All petrol engine cars up from model year 01/2005**

Engine warning light comes on.

If the customer complains that the engine warning light comes on, the fault code P0030 (heated lambda probe 1, cylinder row 1, heating control circuit malfunction) may be stored.

The cause of the problem may be a poor production quality of solder joints in the wiring harness.

Possible cause:

- Interruption or excessive resistance in the wiring harness of the heated lambda probe.
- Interruption or excessive resistance in the wiring harness of the manifold air pressure sensor.

Remedy:

- Check solder joints in the wiring harness.