

Mazda 3/6 - Motoren går periodisk i stå | HELLA

Mazda Modelserie 3/6 Motorkode: PE, PY Årgang: 10/2013 - 02/2014
Motoren går uroligt
Motoren går periodisk i stå
For ovennævnte modeller reklameres der over ukontrolleret motorstop.
En mulig årsag kan være en softwarefejl i motorstyreenheden.
En ukorrekt aktivering af brændstofpumpen medfører utilstrækkelig brændstofforsyning, urolig motorgang og evt. at motoren går ud.
Kan der ikke fastslås andre årsager, skal softwareversionen kontrolleres og evt. opdateres.
Opdateringen kan kun udføres i et autoriseret værksted.
Reparationsvejledning: Bilfabrikanten har allerede taget sig af problemet, og brugerne af de berørte biler er underrettet.
Det må dog antages, at ikke alle biler er blevet kontrolleret eller repareret.
Berørte modeller: 3 stelnr.: JJMZGJ**21154413 til -1697156 stelnr.: JMZBM****21124994 til -140890**

3/6 series

Engine code: PE, PY

Year of construction: 10/2013 – 02/2014

Engine not running smoothly

Engine stalls sporadically

There have been complaints of unexpected engine stalling in the aforementioned vehicles.

This may be due to a software error in the engine control unit.

Incorrect control of the fuel pump leads to an insufficient fuel supply, the engine not running smoothly, and stalling.

If no other cause can be found, the software version must be checked and updated if necessary.

The update can only be carried out by an authorized garage.

<u>Repair note:</u>

The vehicle manufacturer has already addressed the issue and notified the owners of all the affected models.

However, it can be assumed that not all vehicles have been inspected and repaired.

Affected vehicles:

3-series chassis nos. :JMMZGJ****21154413 to 169715

6-series chassis nos. :JMZBM****21124994 to 140890