

# Mercedes Benz ML 270 CDI - Engine control light is on | HELLA

**Mercedes Benz**

**Model year: 11.1999 - 06.2005**

**Engine: OM 612,963**

If one or more of the above problems are identified on this vehicle model, this may be associated with a broken linkage of the charge duct control. In this case, the linkage must be removed and replaced with a spare part modified by the vehicle manufacturer.

