

Opel Astra J - Forsinkede advarsels- og blinklyde | HELLA

Opel Astra-J Årgang: fra 2010
Radio: CD300 / CD400 / CDC400
Forsinkede advarsels- og blinklyde
Forsinkede advarselstoner fra parkeringsassistenten
Hvis der for disse modeller klages over, at advarsels- og blinklydene hhv. tonerne fra parkeringsassistenten lyder med forsinkelse, kan årsagen være en softwarefejl.
Berørte radiomodeller med forsinket tonegivning for blinklys og parkeringsassistent: CD300; CD400; CDC400.
Bilfabrikanten har allerede taget sig af problemet, og brugerne af de berørte biler er underrettet. Man må dog af diverse grunde gå ud fra, at ikke alle biler er blevet kontrolleret eller udbedret.
Fra og med august 2012 har fabrikanten indført en forbedret software.

Astra J

Model year: 2010 onwards

Radio: CD300 / CD400 / CDC400

Delayed warning and indicator tones.

Delayed warning tones for the parking aid.

If it is reported that warning, indicator or parking aid tones are providing delayed notification for these vehicles, a deviation in the software should be considered as a potential cause.

Radio models affected with delayed tone playback for indicators and the parking aid: CD300; CD400; CDC400.

The vehicle manufacturer has already recognized the problem and has corrected it using a software update. It must be assumed, however, that for a variety of reasons not all vehicles have been checked or repaired.

Improved software has been in use at the vehicle manufacturer since August 2012.