

Opel Astra J - Kortslutning i kølerventilator | HELLA

Opel Astra J Årgang: 2010 - 2012 Motor: A14 XEL/XER/NET + X16 XER/LET
Kortslutning i kølerventilator
Kølerventilator-modul defekt
ovennævnte modeller kan der opstå kortslutning i kølerventilatoren og beskadigelse af ventilatormodulet. For at forhindre dette skal der efterfølgende foretages ændringer af ledningsnettet. Det gælder modeller med følgende stelnumre: A 3 001367 - B 3 023589 (fabrik St. Petersburg) A G 000001 - C G 000009 (fabrik Gliwice) A 8 000004 - C 8 000013 (fabrik Ellesmere Port)
Alt efter kølemodul monteres der i motorrummet et adapter-lednings sæt, som tilsluttes til sikringsboksen. Yderligere oplysninger fås hos de autoriserede forhandlere.

Astra J

Model year: 2010–2012

Engine: A14 XEL/XER/NET + X16 XER/LET

Radiator fan short circuit

Radiator fan module defective

In the vehicles mentioned above, the radiator fan may short-circuit, damaging the fan module. This is prevented by making modifications to the wiring harness.

Vehicles with the following chassis numbers are affected:

A 3 001367 - B 3 023589 (St. Petersburg plant)

A G 000001 - C G 000009 (Gliwice plant)

A 8 000004 – C 8 000013 (Ellesmere Port plant)

Depending on which engine cooling module the vehicle has, an adapter wiring harness is installed in the engine compartment and connected to the fuse box. For more information, please contact your authorized dealer.