

# Opel Meriva B - Forsinket afgivelse af signaltoner | HELLA

**Opel Meriva B Årgang: 2010 - 2012 Med radio CD/CDC 300+400**  
**Blinklys og parkeringsassistent Forsinket afgivelse af**  
**signaltoner** I ovennævnte modeller kan en softwarefejl medføre  
forsinket afgivelse af advarsels-og blinktoner samt toner fra  
parkeringsassistenten. Hvis tonefunktionen fungerer med  
forsinkelse, kan problemet løses med en ændret software. Hertil skal  
man henvende sig til et autoriseret mærkeværksted. Kun modeller,  
der er udstyret med radio-CD hhv. CDC af type 300 og 400, er berørt.

**Meriva B**

**Model year: 2010 - 2012**

**With radio-CD/CDC 300+400**

On the above mentioned vehicles, the playback of the warning, direction indicating sounds and the sounds for the parking aid may be delayed due to a software bug.

If the audio function operates with a certain delay, modified software may rectify the problem. Contact one of the vehicle manufacturer's dealers on this issue.

Only vehicles equipped with a radio-CD or CDC

of the type 300 and 400 are affected.