

VW Eos- Kabinebelysningen tænder under kørslen | HELLA

VWEos Årgang: 05/2006 – 11/2010 Kabinebelysningen tænder under kørslen. Hvis ovenstående fejl konstateres på ovennævnte model, kan det skyldes en funktionsfejl i kontakten til havariblinket. Desuden kan der forekomme en funktionsfejl i centrallåsen -- den åbner hhv. låser af sig selv under kørslen --. **Reparationsanvisning-** Kontroller styreenheden til centrallåsen for evt. posteringer i fejlhukommelsen. (Fejlkode: 0556/ Åbning via kollisions-signal)- Kontroller airbag-styreenheden for evt. posteringer i fejlhukommelsen.- Kontroller ledningerne til styreenheden til centrallåsen.- Kontroller ledningerne til airbag-styreenheden. **Afhjælpning:** Kontroller havariblinkkontaktens funktion, udskift den om nødvendigt.

Eos

Model years: 05/2006 – 11/2010

Interior lighting activates while driving

If the indicated problem occurs in above vehicle, a malfunction of the hazard warning switch might be a possible cause.

The central locking system might also be malfunctioning -- it unlocks and locks by itself while driving --

Repair notes

- Check control unit for central locking system for possible error memory entry. (Error code: 0556/ unlocking triggered by crash signal)
- Check airbag control unit for possible error memory entry.
- Check electric connection cable central locking system control unit.
- Check electric connection cables of airbag control unit.

Remedy:

Check hazard warning switch functionality and replace if necessary.