



# Opel Astra K - unable to deactivate start/stop system

| Data sheet          |                                                |
|---------------------|------------------------------------------------|
| Manufacturer        | Opel                                           |
| Vehicle model       | Astra K                                        |
| Engine              | 1.4l 16V Turbo with start/stop system (B14XFT) |
| Year of manufacture | 2019                                           |
| Symptoms            | Unable to deactivate start/stop system         |

## Important safety note

## Unable to deactivate start/stop system

The following problem is observed in the vehicles mentioned above: unable to deactivate start/stop system.

This is caused by a software error in the engine control unit.

Please proceed as follows to rectify the problem:

- Update software

Subsequently run a fault code query and go for a test drive to check the measure.

Please note that this activity must be exclusively carried out by an authorised specialist workshop and the vehicle manufacturer's repair specifications must always be observed!

Reprinting, distribution, reproduction, exploitation in any form or disclosure of the contents of this document, even in part, is prohibited without our express, written approval; indication of the document source is also required. The schematic illustrations, pictures and descriptions serve only

for the purposes of explanation and representation of the instructions and cannot be used as a basis for installation or assembly work. All rights reserved.