

Isuzu Trooper - Starter does not function

Isuzu

Trooper

Models: 1992 to 1998

With automatic transmission:

Starter does not function

(Automatic transmission is in [N] neutral).

If there are complaints for the above vehicles that the start does not function or activate (even though the automatic transmission selector is in [N] neutral), a possible cause could be a failure of the automatic transmission lockout switch.

To remedy this problem, check the automatic transmission lockout switch and replace it if necessary.

Automatic transmission lockout switch spare part Number:

1 unit: Spare part no.: 8-96017-178-0