

Fasci luminosi / distribuzione della luce dei fari | HELLA

Skoda Octavia anno: 2010

Fari allo xenon

I risultati delle misurazioni della distribuzione della luce della lampada frontale allo xenon di una Skoda Octavia costruita nel 2010 sono indicativi. Prima di effettuare la prova, devono essere rispettate anche in questo caso le prescrizioni per una corretta posizione di regolazione del proiettore.

Fasci luminosi / distribuzione della luce con impostazione o.k.

- luce anabbagliante + abbagliante
- centrafari analogico + digitale











Fig.1

Fig.1: vista anteriore del veicolo

Centrafari: analogico





Fasci luminosi - Distribuzione della luce



Centrafari / analogico

Fig.2: - anabbagliante; xenon;

Fig.3: - abbagliante; alogeno H1

Fig.2; anabbagliante; sinistro

Fig.3; abbagliante; sinistro



Fasce luminose - Distribuzione della luce

Centrafari / analogico

Fig.4: - anabbagliante; xenon

Fig.5: - abbagliante; alogeno H1;

Fig.4; anabbagliante; destro

Fig.5; abbagliante; destro

Skoda Octavia = versione xenon/ alogena

Centrafari: meccanico

D1S/H1

Hella Codice articolo

8GS 009 028-111

8GH 002 089-xxx

Il veicolo deve trovarsi su una superficie di prova piana e soddisfare le norme specifiche del paese.

Attenersi alle indicazioni del costruttore del veicolo.

Postazione di regolazione dei fari

Beamsetter / analog

Figure 4: - Low beam; xenon

Figure 5: - High beam; halogen H1;

Figure 4; Low beam; right

Figure 5; High beam; right

Skoda Octavia = xenon/ halogen - version

Beam setting: mechanical

D1S/H1

Hella article no.

8GS 009 028-111

8GH 002 089-xxx

The vehicle must stand on a level test surface and comply with country-specific regulations.

Observe the vehicle manufacturer's instructions.

Headlamp adjustment location

Centrafari: digitale / basato su fotocamera





Light patterns - light distribution

Beamsetter /

digital - camera-based


Figure 6: - Low beam; xenon;

Figure 7: - High beam; halogen H1;

Figure 6; Low beam; left

Figure 7; High beam; left

Skoda Octavia Bj.: 2010 _ Xenon



Skoda Octavia Bj.: 2010 _ Xenon/ Halogen



Light patterns - light distribution

Beamsetter /

digital -- camera-based

Figure 8: - Low beam; xenon

Figure 9: - High beam; halogen H1;

Figure 8; Low beam; right

Figure 9; High beam; right





Important:

- Ensure correct battery voltage, connect charger if necessary (Figure 10).

Figure 11

Inclination 1%

Figure 10

Figure 11





Important:

- Perform visual inspection and technical check of headlamp.

Recommendation:

- Replace faulty light sources in pairs

Beamsetter IV -- analog --

Beamsetter V – digital --

Important safety note

Technical information and practical tips have been compiled by HELLA in order to provide professional support to vehicle workshops in their day-to-day work. The information provided on this website is intended for use by suitably qualified personnel only.