

VW Golf IV - Función de aire circulante | HELLA

VW

Golf IV

Con aire acondicionado manual

Función de aire circulante

En los vehículos arriba mencionados puede producirsebr /> un fallo en la función de aire circulante.

En los vehículos arriba mencionados, el testigo luminoso de control del interruptor del aire circulante (imagen) puede fallar de manera prematura. Ello puede llevar a pensar en un fallo eléctrico del interruptor.

Antes de sustituir el interruptor o de realizar una búsqueda del fallo más exhaustiva, debería comprobarse si la lámpara del interruptor funciona y renovarla si es necesario.



The reprinting, distribution, reproduction, exploitation in any form and disclosure of the contents of this document, even in part, is prohibited without our express written approval and indication of the source. The schematic illustrations, figures and descriptions are for explanation and presentation of the document text and cannot be used as a basis for installation or design. All rights reserved.