

# **Opel Mokka - GPS not functioning | HELLA**

**Opel**

**Mokka**

**Model year: 2013**

**Vehicle Identification Number: DB000001 – BD033498**

## **GPS not functioning**

The GPS symbol is crossed out when shown in the display.

There may be incorrect country allocation during navigation.

If the above error messages are displayed, this may be due to incorrect connection of the cable to the aerial base.

The aerial base in the affected vehicles is replaced with a correctly wired base in the specialist workshop.

The vehicle manufacturer has already addressed the issue.

The manufacturer states that correctly wired antenna bases are being used in production from Vehicle Identification Number: WOLJC7EL2DB033498.